

KUT 6	KST 6WS	KUT 10	KUT 16	KUT 25
8 mm (0.31 Inch)	8 mm (0.31 inch)	10 mm (0.39 inch)	12 mm (0.47 inch)	12 mm (0.47 inch)
46.4 x 42.5 (1.83 x 1.67)	49.8 x42.5 (1.96 x 1.67)	46.4 x 42.5 (1.83 x 1.67)	51 x 44.5 (2.01 x 1.75)	56 x 45 (2.2 x 1.77)
6 sq mm	6 sq mm	10 sq mm	16 sq mm	25 sq mm
0.5 sq mm - 6 sq mm	0.5 sq mm - 6 sq mm	1.5 sq mm - 10 sq mm	6 sq mm - 16 sq mm	6 sq mm - 25 sq mm
0.5 sq mm - 10 sq mm	0.5 sq mm - 10 sq mm	1.5 sq mm - 16 sq mm	6 sq mm - 25 sq mm	6 sq mm - 25 sq mm
12 mm	12 mm	12 mm	15 mm	15 mm
2 screw clamp & 1 tapped hole for cross connection	2 screw clamp & 1 tapped hole for cross connection	2 screw clamp and 1 tapped hole for cross connection	2 screw clamp & 1 tapped hole for cross connection	2 screw clamp & 1 tapped hole for cross connection
800 V/41A/6 sq mm/0.8 Nm 600 V/50 A/8-20 AWG/14 Lbln	630 V/41A/6 sq mm/0.8 Nm 600 V/40 A/8-20 AWG/12 Lbln	800 V/57 A/10 sq mm/1.2 Nm 600 V/65 A/6-16 AWG/14 Lbln	800 V/76 A/16 sq mm/1.2 Nm 600 V/100 A/3-12 AWG/17 Lbln	1000 V/101 A/25 sq mm/2.3 Nm 600 V/115 A/2-10 AWG/20 Lbln
M3.5	M3.5	M4	M4	M5



KUT 6			KST 6WS			KUT 10			KUT 16			KUT 25		
CAT #	STD. PKG.	WT/STD.PKG-KG	CAT #	STD. PKG.	WT/STD.PKG-KG	CAT #	STD. PKG.	WT/STD.PKG-KG	CAT #	STD. PKG.	WT/STD.PKG-KG	CAT #	STD. PKG.	WT/STD.PKG-KG
KUT 6	100	1.51	KST 6 WS	100	1.60	KUT 10	100	2.07	KUT 16	100	2.70	KUT 25	50	1.83
KPX	100	0.31	KSP 6WS	100	0.52	KPX	100	0.31	KPY	100	0.37	KP T	100	0.45
KBX	100	0.46	KBY	100	0.43	KBX	100	0.46	KB Y	100	0.43	KB T	100	0.56
KBXF	100	0.54	KBXF	100	0.54	KBXF	100	0.54	KBZF	100	0.75	KBZF	100	0.75
SCKN	100	0.80	SCKN	100	0.80	SCKN	100	0.80	SCKN	100	0.80	SCKN	100	0.80
SCUN	100	0.94	SCUN	100	0.94	SCUN	100	0.94	SCUN	100	0.94	SCUN	100	0.94
SCUSL	50	0.63	SCUSL	50	0.63	SCUSL	50	0.63	SCUSL	50	0.63	SCUSL	50	0.63
SCUDD	50	0.64	SCUDD	50	0.64	SCUDD	50	0.64	SCUDD	50	0.64	SCUDD	50	0.64
CCLA 6 -2W	100	0.58	CCLA 6 - 2W	100	0.58	CCLA 10-2W	100	0.76	CCLA 16 - 2W	100	0.83	CCLA 25- 2W	100	0.83
CCLA 6 -3W	100	0.86	CCLA 6 - 3W	100	0.86	CCLA 10-3W	100	1.16	CCLA 16 - 3W	100	1.24	CCLA 25- 3W	100	1.24
CCLA 6 -4W	50	0.58	CCLA 6 - 4W	50	0.58	CCLA 10-4W	50	0.78	CCLA 16 - 4W	50	0.83	CCLA 25- 4W	50	0.83
CCLA 6 -5W	50	0.71	CCLA 6 - 5W	50	0.71	CCLA 10-5W	50	0.98	CCLA 16 - 5W	50	1.04	CCLA 25- 5W	50	1.04
CCLA 6 -10W	25	0.72	CCLA 6 - 10W	25	0.72	CCLA 10-10W	25	0.98	--	--	--	--	--	--
PSL 6 - 2W	100	0.08	PSL 6 - 2W	100	0.08	PSL 10-2W	100	0.11	PSL 16 - 2W	100	0.20	PSL 16 - 2W	100	0.20
PSL 6 - 3W	100	0.12	PSL 6 - 3W	100	0.12	PSL 10-3W	100	0.18	PSL 16 - 3W	100	0.30	PSL 16 - 3W	100	0.30
PSL 6 - 4W	100	0.16	PSL 6 - 4W	100	0.16	PSL 10-4W	100	0.23	PSL 16 - 4W	100	0.40	PSL 16 - 4W	100	0.40
PSL 6 - 5W	100	0.20	PSL 6 - 5W	100	0.20	PSL 10-5W	100	0.28	PSL 16 - 5W	100	0.50	PSL 16 - 5W	50	0.25
PSL 6 - 10W	50	0.20	PSL 6 - 10W	50	0.20	PSL 10-10W	100	0.55	--	--	--	--	--	--
SSP2.5 - 6	100	0.27	SSP2.5-6	100	0.27	SSP10-16	100	0.32	SSP10 -16	100	0.32	SSP 10 -16	100	0.32
SLC 6 -2W	100	0.27	SLC 6 -2W	100	0.27	--	--	--	--	--	--	--	--	--
SLC 6 -3W	100	0.43	SLC 6 -3W	100	0.43	--	--	--	--	--	--	--	--	--
SLC 6 -4W	100	0.59	SLC 6 -4W	100	0.59	--	--	--	--	--	--	--	--	--
SLC 6 -5W	50	0.36	SLC 6 -5W	50	0.36	--	--	--	--	--	--	--	--	--
SLC 6 -10W	50	0.75	SLC 6 -10W	50	0.75	--	--	--	--	--	--	--	--	--
RSL 6	100	0.06	RSL 6	100	0.06	RSL 10	100	0.11	RSL 16	100	0.16	RSL 25	100	0.22
LSR 10-16	100	0.49	LSR2.5-6	100	0.31	LSR10-16	100	0.49	LSR 10-16	100	0.49	LSR 25	100	0.75
Label KN 8	100 Strips	0.12	Label KN 8	100 Strips	0.12	Label KN 10	100 Strips	0.15	Label KN 10	100 Strips	0.15	Label KN 10	100 Strips	0.15
WL 6	100	0.32	WL 6	100	0.32	WL 10	100	0.42	WL 16	100	0.52	WL 16	100	0.52
SCKNMLH	50	0.55	SCKNMLH	50	0.55	SCKNMLH	50	0.55	SCKNMLH	50	0.55	SCKNMLH	50	0.55
SCUNMLH	50	0.60	SCUNMLH	50	0.60	SCUNMLH	50	0.60	SCUNMLH	50	0.60	SCUNMLH	50	0.60
KUT6(G), KUT6(K)			KST6WS(G), KST6WS(K)			KUT10(G), KUT10(K)			KUT16(G), KUT16(K)			KUT25(G), KUT25(K)		
KUT6(R), KUT6(Y), KUT6(B)			KST6WS(R), KST6WS(Y), KST6WS(B)			KUT10(R), KUT10(Y), KUT10(B)			KUT16(R), KUT16(Y), KUT16(B)			KUT25(R), KUT25(Y), KUT25(B)		
KUT6(BL), KUT6(GR)			KST6WS(BL), KST6WS(GR)			KUT10(BL), KUT10(GR)			KUT16(BL), KUT16(GR)			KUT25(BL), KUT25(GR)		
CHS 3/5/10	100/100/50	22/37/36	CHS 3/5/10	100/100/50	22/37/36	CHS 3/5/10	100/100/50	22/37/36	CHS 3/5/10	100/100/50	22/37/36	CHS 3/5/10	100/100/50	22/37/36
CHK 3/5/10	100/100/100	11/19/36	CHK 3/5/10	100/100/100	11/19/36	CHK 3/5/10	100/100/100	11/19/36	CHK 3/5/10	100/100/100	11/19/36	CHK 3/5/10	100/100/100	11/19/36
CHKS 3/5/10	100/100/100	11/17/34	CHKS 3/5/10	100/100/100	11/17/34	CHKS 3/5/10	100/100/100	11/17/34	CHKS 3/5/10	100/100/100	11/17/34	CHKS 3/5/10	100/100/100	11/17/34
CHKDS 10	50	34.50	CHKDS 10	50	34.50	CHKDS 10	50	34.50	CHKDS 10	50	34.50	CHKDS 10	50	34.50